



START UP PROCESS -

Add **Metal Gone (Whole Bottle)** or **EZ SPA START (Half bottle)** to Remove metals, phosphates, scaling carbonates and organic debris.

When Water Gets 90 Degrees or Higher :

When adjusting Water chemistry **ALWAYS** balance Alkalinity first, then pH, then sanitizer.

Add pH Increaser (Spa Up) or pH Decreaser (Spa Down) as needed to balance Alkalinity and pH.

NOTE: With initial fill ups you will most likely have extremely High pH and Alkalinity once your spa has reached the set temperature. Check Alkalinity and pH with a test strip. Add 1-3 cap fulls of Spa Down to lower alkalinity, until you see a color shift on the test strips. Once you see a color shift then use the recommended dosage on the bottle for your spa to balance alkalinity and pH

Total Alkalinity 80-120 ppm

PH 7.2-7.6

(DO NOT PROCEED UNTIL PH & ALK LEVELS ARE CORRECT)

Add **SPA 56** at a dose of 1/2 oz per 100 gallons.

Add **EZ SPA TOTAL CARE** at a dose of 1oz per 100 gallons. For spas using ozone, mineral purifiers or salt. Add 1/2oz per 100 gallons.

AFTER 24-48 HOURS RINSE THE CARTRIDGE FILTER(s)

WEEKLY:

Add **SPA 56** at a dose of **1 Teaspoon** at the end of each day the spa is used. **(Reduce to ½ Teaspoon if tub is being used daily) If spa is not being used, Spa 56 should be added a minimum of 1x /week at a dosage of 2-3 Tablespoons.**

Test water with a test strip. Adjust PH as Needed. **(Should only take a tablespoon or two)** Make sure this level is correct before proceeding.

Add **EZ SPA TOTAL CARE** at a dose of 1oz per 100 gallons. For spas using ozone, mineral purifiers or salt add only 1/2oz per 100 gallons.

Rinse **CARTRIDGE FILTER(s)**

Additional Water Care:

Water Changes are recommended every 3-6 months, dependant on usage. Daily users will need to do water changes every 3-4 months. People with average usage patterns (3-4 times per week), will be changing their water every 4-6 months.

When refilling your spa, fill through the filter housing to avoid air locks in the pumps. If your home has a water softener make sure your outside spigots are on bypass. The spa water needs to have calcium levels of at least 150-250ppm. Using softened water will cause the water to become corrosive, resulting in damage to the spas components.

Filter(s) should be replaced with new ones every 12-18 months.

More information is available in the spas owners manual.